



**McClelland Concrete Pumping**

ABN: 58 192 160 894

Postal Address PO Box 9787 TOOWOOMBA Q 4350

(Toowoomba) 509 Boundary St TORRINGTON Q 4350

(Dalby) 184 Woodlawn Rd BELL Q 4408

Email admin@mcpumping.com | Phone 0427 631 143

## Pump Summary

Printed: 10-01-2022

<b>Truck</b>		
Truck Make	Assessment Date	Asset ID
<b>Mercedes</b>	<b>10-01-2022</b>	<b>28m</b>
Truck Model	VIN	Plant ID
<b>Axor</b>	<b>WDB9536432L854204</b>	<b>MC16</b>
Serial Number	Registration Date	Registration Number
<b>1018317</b>	<b>29-12-2021</b>	<b>275WXU</b>
Last Serviced Hours	Current Hours	Next Service
<b>9693.0</b>	<b>9993.0</b>	<b>10043.0</b>
<b>12-08-2021</b>		
Manufacture Date	Date Fire Extinguisher Tested	First Aid Kit Check Date
<b>2014</b>	<b>10-01-2022</b>	<b>10-01-2022</b>
<b>Pump</b>		
Plant Registration	<b>P0074180</b>	
Commissioned Year	<b>2014</b>	
Pump Brand	Current Pump Hours	Next Service/Inspection Due
<b>Schwing</b>	<b>1324.0</b>	<b>1691</b>
Pump Model	Annual Cubic Metres Pumped	Total Cubic Metres Pumped
<b>28XL</b>	<b>32960.0</b>	<b>39827.0</b>
<b>Boom</b>		
Boom Brand	Annual Inspection Due Date	Last Annual Inspection Hours
<b>Schwing</b>	<b>01-02-2022</b>	<b>1191.0</b>
Boom Model	Last 6 Yearly Inspection Date	6 Yearly Inspection Due Date
<b>28CX</b>	<b>19-12-2018</b>	<b>19-12-2024</b>
Outrigger Dunnage:	<b>13/10</b>	