



Monthly Pipeline Thickness Test & Inspection

43889

1 of 4
White: Office Copy
Blue: Logbook Copy

By completing this check you are indicating you are competent person under Clause 1.3.2.3 of AS2550.15.

COMPANY McKellard C.P PUMP MODEL / TYPE JXZ37-4.16

BOOM TYPE / SIZE 37M SERIAL NO. 911 INSPECTION YEAR 2023

UNIT NO. MU 12

Pipe Description	Min. Allowable Thickness (mm)	Date Fitted	ID Tag No.	Testing Results and Inspection Month											
				Aug	Sep	Oct	Nov	Dec	Jan	Feb	Mar	April	Month	Month	
1. Swinging 90°		1 1		15.1	15	15	14.8	14.5	14.5	14.4	14.4	14.3			
2. Elbow		03/09/20		9	9	8.9	8.8	8.5	8.5	8.4	8.4	8.3			
3. 6"-5" Reducer		03/09/20		5.3	5.3	5.2	5.2	5	5	4.8	4.7	4.6			
4. 45° 37.5°		03/09/20		4	4	3.9	5.7	5.8	5.8	5.7	5.7	5.6			
5. Deck Pipe 1		1 1		6.3	12	11.9	6.9	6.7	6.7	6.6	6.6	6.5			
6. Deck Pipe 11		25/10/20		4	4	3.9	4.5	4.4	4.4	4.3	4.3	4.2			
7. Deck Pipe 111		25/10/20		3.5	3.5	3.4	14	13.9	13.9	13.8	13.6	13.7			
8. 90° Elbow		1 1		4.9	4.8	4.5	5.9	5.8	5.8	5.7	5.7	5.6			
9. Turret Upright		03/09/20	20.11.21	3.9	3.9	3.5	3.8	3.7	3.7	10.5	10.5	10.4			
10. 90° Elbow		03/09/20		3.9	3.9	3.3	5.8	5.7	5.7	4.8	4.8	4.7			
11. 300 mm		26/10/21		4.9	4.8	4.8	4.7	4.6	4.6	4.6	4.6	4.5			
12. 90° Elbow		1 1		4.4	4.4	3.9	5.9	3.9	3.9	5.8	5.7	3.6			
13. Stage 1, Pipe 1		14/08/20		2.4	2.4	2	5.9	5.8	5.8	5.7	5.6	5.5			
14. Stage 1, Pipe 11		25/10/21		2.7	2.6	2.6	2.6	2.5	2.5	3.7	3.6	3.5			
15. Stage 1, Pipe 111		1 1		DS	DS	DS	DS	DS	DS	DS	DS	DS			

Competent Person Completing Inspection (Initials)

By completing this check you are indicating you are competent person under Clause 1.3.2.3 of AS2550.15.

COMPANY McClelland Concrete Pumping UNIT NO. MC 12
 BOOM TYPE / SIZE 32m SERIAL NO. 911

PUMP MODEL / TYPE JX737-4.16
 INSPECTION YEAR 2022

Pipe Description	Min. Allowable Thickness (mm)	Date Fitted	ID Tag No.	Testing Results and Inspection Month												
				Aug	Sep	Oct	Nov	Dec	Jan	Feb	March	April	Month	Month		
16. 90° Elbow		3/1/22		3.6	3.6	3.5	3.5	3.9	3.9	3.9	3.9	3.9	3.9	3.9	13.8	13.8
17. 90° Elbow		5/1/11		3.9	3.9	3.8	3.5	3.9	3.9	3.9	3.9	3.9	3.9	3.9	13.8	13.8
18. Stage II, Pipe I		14/08/20		4.4	4.3	4.5	4.3	4.2	4.2	4.2	4.1	4.1	4.1	4.1	4	4
19. Stage II, Pipe II		1/1		3	3	3	3	2.9	2.9	2.3	2.1	2.1	2.1	2.1	5.3	5.3
20. Stage II, Pipe III		11/09/20		5.3	5.3	5.2	5.1	5	5	5	4.9	4.9	4.9	4.9	4.7	4.7
21. 90° Elbow		1/1		3.9	3.9	3.8	3.8	3.7	3.7	3.7	3.6	3.6	3.6	3.6	5.4	5.4
22. 90° Elbow		1/1		3.9	3.9	3.8	3.8	3.7	3.7	3.7	3.6	3.6	3.6	3.6	3.4	3.4
23. Stage III, Pipe I		1/1		5.6	5.5	5.5	5.4	5.3	5.3	5.3	5.2	5.2	5.2	5.2	5.1	5.1
24. Stage III, Pipe II		1/1		5.2	5.2	5.1	5.1	5.0	5.0	5.0	4.9	4.9	4.9	4.9	2.8	2.8
25. Stage III, Pipe III		1/1		3.1	3.1	3	3	2.9	2.9	2.8	2.8	2.8	2.8	2.8	2.7	2.7
26. 90° Elbow		1/1		10.3	10.3	10.2	10.2	10	10	10	9.9	9.9	9.9	9.9	9.8	9.8
27. 90° Elbow		1/1		10.3	10.3	10.2	10.2	10	10	10	9.9	9.9	9.9	9.9	9.8	9.8
28. Stage III, Pipe I		1/1		4.2	4.2	4.1	4.1	4	4	4	3.9	3.9	3.9	3.9	3.7	3.7
29. Stage III, Pipe II		4/1/21		5.5	5.5	5.4	5.4	5.3	5.3	5.3	5.2	5.2	5.2	5.2	5.1	5.1
30. Stage III, Pipe III		4/1/21		5.5	5.5	5.4	5.4	5.3	5.3	5.3	5.2	5.2	5.2	5.2	5.1	5.1
Competent Person Completing Inspection (Initials)				DS	DS	DS	DS	DS	DS	DS	DS	DS	DS	DS	DS	DS

3491

43889

Monthly Pipeline Thickness Test & Inspection

By completing this check you are indicating you are competent person under Clause 1.3.2.3 of AS2550.15.

PUMP MODEL / TYPE: SXZ 37-4.16

INSPECTION YEAR: 21

COMPANY: Mc Gillivray Concrete Paving UNIT NO. PPCA

SERIAL NO.: 911

BOOM TYPE / SIZE: 37 M

Pipe Description	Min. Allowable Thickness (mm)	Date Fitted	ID Tag No.	Testing Results and Inspection Month													
				Aug	Sep	Oct	Nov	Dec	Jan	Feb	March	April	Month	Month			
31. 90° Elbow		/ /		11.6	11.6	11.5	11.4	11.3	11.2	11.1	11.1						
32. 90° Elbow		/ /		11.5	11.5	11.4	11.4	11.3	11.2	11.1	11.1						
33.		/ /															
34.		/ /															
35.		/ /															
36.		/ /															
37.		/ /															
38.		/ /															
39.		/ /															
40.		/ /															
41.		/ /															
42.		/ /															
43.		/ /															
44.		/ /															
45.		/ /		DS	DS	DS	DS	DS	DS	DS	DS	DS	DS	DS	DS	DS	DS

Competent Person Completing Inspection (Initials)

3411