



**McClelland Concrete Pumping**

ABN: 58 192 160 894

**Postal Address** PO Box 9787 TOOWOOMBA Q 4350  
 (Toowoomba) 509 Boundary St TORRINGTON Q 4350  
 (Dalby) 184 Woodlawn Rd BELL Q 4408

**Email** admin@mcpumping.com | **Phone** 0427 631 143

## Pump Summary

Printed:

<b>Truck</b>		
Truck Make	Assessment Date	Asset ID
<b>DAF</b>	<b>11-09-2023</b>	<b>42m20</b>
Truck Model	VIN	Plant ID
<b>CF7585</b>	<b>XLRAD85MCFG059564</b>	<b>MC20</b>
Serial Number	Registration Date	Registration Number
<b>1044</b>	<b>27-01-2023</b>	<b>XQ39QR</b>
Last Serviced Hours	Current Hours	Next Service
<b>12004.0</b>	<b>12075.0</b>	<b>12354.0</b>
<b>29-08-2023</b>		
Manufacture Date	Date Fire Extinguisher Tested	First Aid Kit Check Date
	<b>07-07-2023</b>	<b>07-07-2023</b>
Modification Approval	Modification Certification	
<b>04-02-2016</b>		
<b>Pump</b>		
Plant Registration	<b>P0088942</b>	
Commissioned Year	<b>2016</b>	
Pump Brand	Current Pump Hours	Next Service/Inspection Due
<b>42m Everdigm</b>	<b>2679.0</b>	<b>2713</b>
Pump Model	Annual Cubic Metres Pumped	Total Cubic Metres Pumped
<b>ECP42CX</b>	<b>0.0</b>	<b>39456.2</b>
<b>Boom</b>		
Boom Brand	Annual Inspection Due Date	Last Annual Inspection Hours
<b>Everdigm</b>	<b>02-02-2023</b>	<b>1646.0</b>
Boom Model	Last 6 Yearly Inspection Date	6 Yearly Inspection Due Date
<b>CD542</b>	<b>05-08-2022</b>	<b>05-08-2028</b>
Outrigger Dunnage:	<b>230F/180R KN</b>	

E&OE

www.mcclellandconcretepumping.com

**Annual Inspection Certificate**

**6-Yearly Inspection Certificate**

**Plant Registration Certificate**

**Road Registration**

**Risk Assessment**

**Pre-Start Inspection**

**Pre\_operational Inspections**

**Pipe Thickness Tests**

## Monthly Maintenance