



**McClelland Concrete Pumping**

ABN: 58 192 160 894

Postal Address PO Box 9787 TOOWOOMBA Q 4350

(Toowoomba) 509 Boundary St TORRINGTON Q 4350

(Dalby) 184 Woodlawn Rd BELL Q 4408

Email admin@mcpumping.com | Phone 0427 631 143

## Pump Summary

Printed: 03-05-2022

<b>Truck</b>		
Truck Make	Assessment Date	Asset ID
<b>DAF</b>	<b>03-05-2022</b>	<b>47m</b>
Truck Model	VIN	Plant ID
<b>FACF85</b>	<b>XLRAD85MCHG167158</b>	<b>MC22</b>
Serial Number	Registration Date	Registration Number
<b>1086</b>	<b>23-02-2023</b>	<b>XQ29YC</b>
Last Serviced Hours	Current Hours	Next Service
<b>2646.0</b>	<b>2891.0</b>	<b>2996.0</b>
<b>02-02-2022</b>		
Manufacture Date	Date Fire Extinguisher Tested	First Aid Kit Check Date
<b>2018</b>	<b>02-02-2022</b>	<b>02-02-2022</b>
Modification Approval	Modification Certification	
<b>16-05-2018</b>	<b>937895/MA1103</b>	
<b>Pump</b>		
Plant Registration	<b>P0091946</b>	
Commissioned Year	<b>2022</b>	
Pump Brand	Current Pump Hours	Next Service/Inspection Due
<b>Everdigm</b>	<b>1338.0</b>	<b>3258</b>
Pump Model	Annual Cubic Metres Pumped	Total Cubic Metres Pumped
<b>ECP47CX</b>	<b>38372.0</b>	<b>43010.0</b>
<b>Boom</b>		
Boom Brand	Annual Inspection Due Date	Last Annual Inspection Hours
<b>Everdigm</b>	<b>27-01-2023</b>	<b>1258.0</b>
Boom Model	Last 6 Yearly Inspection Date	6 Yearly Inspection Due Date
<b>ECP47CX</b>	<b>02-06-2016</b>	<b>02-06-2022</b>
Outrigger Dunnage:	<b>320F/25R kN</b>	