

PL17 PLANT PRE-START INSPECTION - 325RMP

Type and Make	Assessment Date	Asset ID
Transcrete on Isuzu	10-12-2021	LP1
Model	Serial Number	PLANT ID
P60 / FRR	CL050519	P60

IS THE PLANT A CONCRETE BOOM PUMP?	Yes	Х	No	If Yes see section below	
CONCRETE BOOM PUMP - COPIES REQUIRE	D				
Register-able plant current & provided?					Yes
Annual inspection provided?					Yes
Monthly boom checks provided?					Yes
Monthly pipe thickness provided?					Yes

REQUIREMENTS	PRES	PRESENT		
Detailed pump risk assessment completed & attached	Yes 🛛	No 🗌		
Operation and maintenance manual included with plant	Yes 🛛	No 🗌		
Service history available for the pump (upon request)	Yes 🔀	No 🗌		
Logbook with pump and available for inspection	Yes 🛛	No 🗌		
All safety guards fitted	Yes 🛛	No 🗌		
Seatbelt fitted and in good condition	Yes 🛛	No 🗌		
Fire extinguisher fitted, charged & holds a current tag attached.	Yes 🛛	No 🗌		
Reverse alarm fitted and working (if required onsite)	Yes 🛛	No 🗌		
All vehicle systems operational	Yes 🛛	No 🗌		
Flashing light fitted and working	Yes 🛛	No 🗌		
3-point contact access	Yes 🛛	No 🗌		
Hose burst protection on any hydraulic lifting device	Yes 🛛	No 🗌		
Locking pins in place where required	Yes 🛛	No 🗌		
Earthing chain & spike included (if required onsite)	Yes 🛛	No 🗌		
Engine checks done - no leaks, loose items, faulty items, no smoking exhaust, etc	Yes 🛛	No 🗌		
Perimeter checks done - no cracked windows, tyres good condition, etc	Yes 🛛	No 🗌		

Other - additional attachments that will be used / additional relevant comments

CERTIFICATION BY RESPONSIBLE PERSON i.e. Owner or Owners representative

I certify that the described pump is to the manufacturer's specifications and is being serviced and maintained by competent personnel to the manufacturer's recommendations.

NAME	POSITION	SIGNATURE	DATE				
Wayne McClelland	Owner	W m' - P.	10-12-2021				
TO BE COMPLETED BY SITE SUPERVISOR OR REPRESENTATIVE ON SITE							
RECEIVED ON SITE BY	SIGNATURE	DATE	PLANT STICKER NUMBER				