



## Plant Maintenance Register

Plant ID: <b>WP60</b>	Truck Make/Model: <b>Mitsubishi Fuso FK600</b>	Current Odo: <b>61400.0</b>	Date: <b>06-06-2024</b>
Rego No: <b>XQ82RV</b>	Pump Make/Model: <b>Win WP60</b>	Current Hours: <b>5611.40</b>	Serial No: <b>202101</b>

Date	Hour Meter	Odo	Details	Supplier	Invoice No
06-06-2024	5611		B Service	Pengelleys	
13-02-2024	5100		B Service	Pengellys	
11-01-2024	4952		Headlamp assembly	DT Truck	555501T
24-10-2023	4668	61400	B Service	Pengellys	249654
07-09-2023	4388		Wear sleeves for mixer shaft, pressing discs & pads	Win Engineering	INV00059409
04-08-2023	4169		B Service	Pengellys	248708
03-08-2023		57376	4x Tyres	Wise's Mobile Tyres	CO75488
07-07-2023			AdBlue Filler cap	DT Trucks	548863T
06-07-2023	3987		Wheel alignments	Pengellys	248266
30-06-2023	3975		2x new steer tyres	Wises Tyres	CO73918
16-06-2023	3893		1000 hr service. Replace piston cups, guide rings, change-over ram ball sockets, proximity switch, filters,	WWin Eng	00058425
25-05-2023	3755		B Service	Pengellys	247459
16-05-2023			Service		
21-03-2023	3435		Replace reflectors, wiper blades	Pengelly	246551
22-11-2022	2928	40784	B Service	Pengellys	245310
29-06-2022	2226	32420	B Service	Pengelleys	243551
23-06-2022	2197		Service	Pengelleys	
04-04-2022			water box Proximity switch , E-stop c/w horn	PumpNMechanical	INV-1623
07-02-2022	1468		Replaced paddle shaft, seals & bushes	CPE (Jamie Potter)	
18-01-2022	1397	18100	S Service	Pengelly	241099
11-01-2022	1350		Paddle discs, shaft seal shaft motor seal kit, rock shaft seal kit, paddle shaft shaft bush & housing. [Installed by MCP]	Pump N Mechanical	INV-1558
13-12-2021	1219		Repairs to wiring harness	Royce Auto Electrical	50762
15-11-2021	1127	16869	Registration inspection	TMR	
12-11-2021	1127	16869	Road Worthy Inspection	Pengelly Trucks	239880

Name: **Wayne McClelland**

Signature:

Date: 06-06-2024