



**McClelland Concrete Pumping**

ABN: 58 192 160 894

Postal Address PO Box 9787 TOOWOOMBA Q 4350  
(Toowoomba) 509 Boundary St TORRINGTON Q 4350

Email admin@mcpumping.com | Phone 0427 631 143

## Pump Profile Report

Printed: 06-06-2024

<b>Truck</b>		
Truck Make	Manufacture Date	Asset ID
<b>Mitsubishi</b>	<b>2021</b>	<b>LP2</b>
Truck Model	Assessment Date	Plant ID
<b>Fuso FK600</b>	<b>06-06-2024</b>	<b>WP60</b>
VIN	Road Registration Expires	Registration Number
<b>JLFFK62FH0KJ25459</b>	<b>25-03-2025</b>	<b>XQ82RV</b>
GVM/Tare	Plant Registration Expires	Plant Registration Number
<b>11000 / 8360</b>	<b>19-01-2035</b>	<b>N/A</b>
Modification Approval	Odometer	Last Serviced Hours
<b>02-03-2021</b>	<b>61400.0</b>	<b>5611.0 05-06-2024</b>
Modification Certification	First Aid Kit Check Date	Current Hours
<b>ModCertAccredNums : 55417</b>	<b>07-07-2023</b>	<b>5611.4</b>
	Date Fire Extinguisher Tested	Next Service
	<b>15-01-2024</b>	<b>6061.0</b>
<b>Pump</b>		
Pump Brand	Serial Number	Plant Registration Expires
<b>Win</b>	<b>202101</b>	<b>19-01-2035</b>
Pump Model	Next Service/Inspection Due	Total Cubic Metres Pumped
<b>WP60</b>	<b>1369</b>	<b>7777.7</b>
Commissioned Year		Current Pump Hours
<b>2021</b>		<b>2922.4</b>
<b>Boom</b>		
Boom Brand	Annual Inspection Date	Last Annual Inspection Hours
		<b>369.0</b>
Boom Model	Last 6 Yearly Inspection Date	6 Yearly Inspection Due Date
Outrigger Distance/Load:	<b>N/A</b>	